



Safety Alert Message

U.S. Army Forces Command

During a recent incident in Iraq, three service members were injured, one losing an arm, while removing adhesive tape from the safety device of a DWBS (MK 141 Flash Bang).



Accident Site

MK 141 Flash Bang –
Note the White Band



This munition is **restricted** from use
by all the Services as of 2006

- Do Not tape the safety lever or safety pin!
- Do Not bend, tamper, modify or otherwise alter the safety pin or safety lever
- Grenade safety devices are designed as part of the grenade to keep **YOU** Safe!



NEVER apply or remove tape – Call your supporting QASAS